

SKYLINE FOUNDATIONS AND STRUCTURES PRIVATE LIMITED
TRIVANDRUM
PROJECT WORK PROGRESS REPORT - MONTHLY

Common Area work & Amenities.

| | |
|-----------------|------------|
| Name Of Project | RETREAT |
| Report Date | 03-05-2023 |

| No | Description | Actual Date of Completion | Remarks |
|----|-----------------------------------|---------------------------|---------|
| 1 | C. wall | | 80% |
| 2 | Gate | | 60% |
| 3 | Bore well / Open well | 10.02.2019 | 100% |
| 4 | Drive way PCC / Flooring | | |
| 5 | Yard drains | | |
| 6 | Pest control | | 70% |
| 7 | Parking area grano flooring | | |
| 8 | Car Park- Inc Multi level parking | | |
| 9 | Sump & OHT | | 100% |
| 10 | Main stair handrails | | 100% |
| 11 | Fire stair handrails | | 100% |
| 12 | External plastering | | 99% |
| 13 | Duct plastering | | 100% |
| 14 | Light well plastering | | 100% |
| 15 | Terrace grano flooring | | 50% |
| 16 | Light well ladder & platform | | 100% |
| 17 | Light well roof | | 100% |
| 18 | Terrace sheet roofing | | NA |
| 19 | Duct plumbing | | 80% |
| 20 | Terrace water proofing | | 90% |
| 21 | Terrace plumbing. | | 90% |
| 22 | External plumbing | | 85% |
| 23 | Ty. Lobby flooring | | 98% |
| 24 | Main stair flooring | | 98% |
| 25 | Fire stair flooring | | 98% |
| 26 | Lift architrave | | 98% |
| 27 | Ty. Lobby painting | | 50% |
| 28 | Ty. Lobby false ceiling | | 80% |
| 29 | Aluminium duct doors | | 95% |
| 30 | Fire escape doors | | 85% |
| 31 | C. Area Doors | | 95% |
| 32 | Reticulated gas | | 45% |
| 33 | Fire Fighting | | 95% |
| 34 | H T Electrical | | 95% |
| 35 | Lifts | | 100% |
| 36 | Recreation hall | | 95% |
| 37 | Common Toilet | | 95% |
| 38 | Driver's room | | 50% |
| 39 | Caretaker Room | | 80% |
| 40 | Party hall | | 95% |
| 41 | Swimming pool | | 100% |
| 42 | Entry water feature wall | | 100% |
| 43 | Wheel chair entry to Main lobby | | 50% |

| | | | |
|----|----------------------------------|--|-------------------|
| 44 | Health club | | 100% |
| 45 | Fitness equipments | | 100% |
| 46 | Games room | | 100% |
| 47 | Children's play area | | 60% |
| 48 | Play equipments | | material received |
| 49 | Roof top party area with Sky Pod | | 80% |
| 50 | Car park marking | | 60% |
| 51 | Reflective convex mirror | | |
| 52 | Yard paving | | |
| 53 | Letter box | | material received |
| 54 | Logos | | |
| 55 | Name boards | | |
| 56 | Key Board | | |
| 57 | Guest suit | | |
| 58 | Access card | | 50% |
| 59 | Intercom | | 50% |
| 60 | Video Door phone | | 50% |
| 61 | Solar panel for CA lighting | | ordered |
| 62 | Bio Bin | | ordered |
| 63 | Rain water harvesting | | 90% |
| 64 | S T P | | |
| 65 | Incinerator | | ordered |
| 66 | Entrance lobby door | | 95% |
| 67 | Entrance lobby furniture | | 75% |
| 68 | Entrance lobby art works | | |
| 69 | Land scaping- Arrival Point | | 60% |
| 70 | Land scaping- Terrace Party area | | 90% |
| 71 | | | |
| 72 | | | |
| 73 | | | |
| 74 | | | |
| 75 | | | |