

SKYLINE FOUNDATIONS & STRUCTURES P (LTD)
MONTHLY PROGRESS REPORT

NAME OF PROJECT: SFS AMBER - GREEN BLOCK

| No | ACTIVITY NAME | ACTUAL | REMARK |
|----|--|--------|--------|
| 1 | Demolishing and Removing existing building | 100% | |
| 2 | Earth - Cutting & Removing | 100% | |
| 3 | Piling | 100% | |
| 4 | Pile cap & Plinth beam | 100% | |
| 5 | Sump tank | 100% | |
| 8 | G F Column | 100% | |
| 9 | G F Slab | 100% | |
| 10 | F F Column | 100% | |
| 11 | F F Slab | 100% | |
| 12 | SF column | 100% | |
| 13 | SF slab | 100% | |
| 14 | TF column | 100% | |
| 15 | TF slab | 100% | |
| 16 | FF column | 100% | |
| 17 | FF slab | 100% | |
| 18 | FF column | 100% | |
| 19 | FF slab | 100% | |
| 20 | SF column | 100% | |
| 21 | SF slab | 100% | |
| 22 | SF column | 100% | |
| 23 | SF slab | 100% | |
| 24 | EF column | 100% | |
| 25 | EF slab | 100% | |
| 26 | NF column | 100% | |
| 27 | NF slab | 100% | |
| 28 | T F column | 100% | |
| 29 | TF slab | 100% | |
| 30 | EF column | 100% | |
| 31 | EF slab | 100% | |
| 32 | TF column | 100% | |
| 33 | TF slab | 100% | |
| 34 | 13th column | 100% | |
| 35 | 13th roof slab | 100% | |
| 36 | 14th floor column | 100% | |
| 37 | 14th roof slab | 100% | |
| 38 | terrace column | 100% | |
| 39 | OHT | 100% | |
| 42 | G F Masonry | 99% | |
| 43 | G F Plastering | 99% | |
| 44 | F F Masonry | 99% | |
| 45 | F F Plastering | 99% | |
| 46 | S F Masonry | 99% | |
| 47 | S F Plastering | 99% | |
| 48 | T F Masonry | 100% | |
| 49 | T F Plastering | 100% | |
| 50 | FF masonry | 100% | |
| 51 | FF plastering | 100% | |
| 52 | FF masonry | 100% | |
| 53 | FF plastering | 100% | |
| 54 | SF masonry | 100% | |
| 55 | SF plastering | 100% | |
| 56 | SF masonry | 100% | |
| 57 | SF plastering | 100% | |
| 58 | 8th masonry | 100% | |
| 59 | 8th plastering | 100% | |
| 60 | 9th floor masonry | 100% | |
| 61 | 9th plastering | 100% | |
| 62 | 10th floor masonry | 100% | |
| 63 | 10th plastering | 100% | |
| 64 | 11th floor masonry | 100% | |
| 65 | 11th plastering | 100% | |
| 66 | 12th masonry | 100% | |
| 67 | 12th plastering | 100% | |
| 68 | 13th masonry | 100% | |
| 69 | 13th plastering | 100% | |
| 70 | 14th floor masonry | 100% | |
| 71 | 14th floor plastering | 100% | |
| 72 | terrace masonry | 100% | |
| 73 | terrace internal wall plastering | 100% | |
| 74 | external plastering | 99% | |
| 75 | 3rd floor tiling works | 95% | |
| 76 | 4th floor tiling works | 95% | |
| 77 | 5th floor tiling works | 95% | |
| 78 | 6th floor tiling works | 95% | |
| 79 | 7th floor tiling works | 95% | |
| 80 | 8th floor tiling works | 95% | |
| 81 | 9th floor tiling oworks | 95% | |
| 82 | 10th floor tiling works | 95% | |
| 83 | 11th floor tiling works | 75% | |
| 84 | 12th floor tiling works | 85% | |
| 85 | 13th floor tiling works | 95% | |
| 86 | 14th floor tiling works | 95% | |
| 87 | 3rd floor painting | 50% | |
| 88 | 4th floor painting | 75% | |
| 89 | 5th floor painting | 50% | |
| 90 | 6th floor painting | 50% | |
| 91 | 7th floor painting | 20% | |
| 92 | 8th floor painting | 20% | |
| 93 | 9th floor painting | 15% | |
| 94 | 10th floor painting | 15% | |
| 95 | 11th floor painting | 15% | |
| 96 | 12th floor painting | 15% | |
| 97 | 13th floor painting | | |
| 98 | 14th floor painting | | |

SFS AMBER BLUE BLOCK

[illegible]

SFS AMBER COMMON AREA

| | | |
|----|------------------------------|------|
| 1 | C. wall | 90% |
| 2 | Bore well / Open well | 90% |
| 3 | Yard drains | 75% |
| 4 | Pest control | 98% |
| 5 | Parking area grano flooring | 75% |
| 6 | Car Park | 100% |
| 7 | Sump & OHT | 100% |
| 8 | Main stair handrails | 100% |
| 9 | Fire stair handrails | 100% |
| 10 | External plastering | 99% |
| 11 | Duct plastering | 100% |
| 12 | Light well plastering | 100% |
| 13 | Terrace grano flooring | 100% |
| 14 | Light well ladder & platform | 100% |
| 15 | Duct plumbing | 90% |
| 16 | Terrace water proofing | 100% |
| 17 | Ty. Lobby false ceiling | 70% |
| 18 | Aluminium duct doors | 40% |
| 19 | Reticulated gas | 50% |
| 20 | Fire Fighting | 93% |
| 21 | H T Electrical | 93% |
| 22 | Lifts | 90% |
| 23 | Swimming pool | 70% |
| 24 | Health club | 40% |
| 25 | Indoor childrens play area | 30% |
| 26 | Roof top party area | 45% |