

SKYLINE FOUNDATIONS & STRUCTURES P (LTD)
MONTHELY PROGRESS REPORT

NAME OF PROJECT : SFS SKY GARDEN

REPORT DATE: 02/04/2026

No	ACTIVITY NAME	ACTUAL	REMARK
1	Demolishing and Removing existing building		
2	Earth - Cutting & Removing	98%	lower basement STP
3	Piling	100%	
4	Pile cap & Plinth beam	99%	Lower Basement Ramp area
5	Sump tank	100%	
6	B F Column	98%	Lower Basement Ramp area
7	B F roof Slab	95%	Podium Area
8	G F Column	100%	
9	G F Roof Slab	98%	Podium Area
10	F F Column	100%	
11	F F Roof Slab	95%	Podium Area
12	2nd Floor Column	100%	
13	2nd floor roof slab	100%	
14	3rd Floor columns	100%	
15	3rd floor roof slab	100%	
16	4 th Floor Column	100%	
17	4 th floor roof slab	100%	
18	5 th floor column	100%	
19	5 th floor roof slab	100%	
20	6 th floor column	100%	
21	6 th floor roof slab	100%	
22	7 th floor columns	100%	
23	7 th floor roof slab	100%	
24	8 th floor columns	100%	
25	8 th floor roof slab	100%	
26	9 th floor columns	100%	
27	9 th floor roof slab	100%	
28	10th floor columns	100%	
29	10th floor roof slab	100%	
30	11th floor columns	100%	
31	11th floor roof slab	100%	
32	12th floor columns	100%	
33	12th floor roof slab	100%	
34	13th floor column	100%	
35	13th floor roof slab	100%	
36	14th floor column	100%	
37	14th floor roof slab	100%	
38	15th floor columns	100%	
39	15th floor roof slab	100%	
40	16th floor roof slab(terrace floor)	100%	
	MASONRY		
41	2nd floor masonry	100%	
42	3rd floor masonry	100%	
43	4 th floor masonry	100%	
44	5th floor masonry	100%	
45	6th floor masonry	100%	
46	7th floor masonry	100%	
47	8th floor masonry	100%	
48	9th floor masonry	100%	

49	10th floor masonry	100%	
50	11th floor masonry	100%	
51	12th floor masonry	100%	
52	13th floor masonry	100%	
53	14th floor masonry	100%	
54	15th floor masonry	90%	
	PLASTERING		
54	2nd floor ceiling plastering	100%	
55	3rd floor ceiling plastering	100%	
56	4th floor ceiling plastering	100%	
57	5th floor ceiling plastering	100%	
58	6th floor ceiling plastering	100%	
59	7th floor ceiling plastering	40%	
60	2nd floor wall plastering	100%	
61	3rd floor wall plastering	100%	
62	4th floor wall plastering	100%	
63	5th floor wall plastering	100%	
64	6th floor wall plastering	100%	
65	7th floor wall plastering	100%	
66	8th floor wall plastering	100%	
67	9th floor wall plastering	90%	
	ELECTRICAL		
68	2nd floor electrical switch box fixing	100%	
69	3rd floor electrical switch box fixing	100%	
70	4th floor electrical switch box fixing	100%	
71	5th floor electrical switch box fixing	100%	
72	6th floor electrical switch box fixing	100%	
73	7th floor electrical switch box fixing	100%	
74	8th floor electrical switch box fixing	100%	
75	9th floor electrical switch box fixing	100%	
76	10th floor electrical switch box fixing	100%	
77	11th floor electrical switch box fixing	100%	
78	12th floor electrical switch box fixing	100%	
79	13th floor electrical switch box fixing	50%	
	FLOORING AND DADOING		
80	2A ,sample apartment	95%	work in progress
	BALCONY HAND RAIL FIXING		
81	2nd floor Balcony hand rails fixing	100%	
82	3rd floor balcony handrails fixing	100%	
	COUNTER FABRICATION WORK		
83	2nd floor counter fabrication work	100%	
84	3rd floor counter fabrication work	100%	
	TOILET SUNKEN WATER PROOFING		
85	2nd floor sunken slab water proofing	100%	
86	3rd floor sunken slab water proofing	100%	
87	4th floor sunken slab water proofing	100%	
88	5th floor sunken slab water proofing	100%	
	PLUMBING CORE CUTTING		
89	2nd floor core cutting	100%	
90	3rd floor core cutting	100%	
91	4th floor core cutting	100%	
92	5th floor core cutting	100%	
93	6th floor core cutting	100%	
	INTERNAL PLUMBING		
94	2nd floor internal plumbing	100%	
95	3rd floor internal plumbing	75%	
	FF CORE CUTTING		
96	2nd floor FF core cutting	100%	

97	3rd floor FF core cutting	100%	
98	4th floor FF core cutting	100%	
99	5th floor FF core cutting	100%	

Prepared by
Site in Charge

Approved by