SKYLINE FOUNDATIONS & STRUCTURES P (LTD)
MONTHLY PROGRESS REPORT

NAME OF PROJECT: CASABELLA
REPORT DATE: 05/11/2026

No	ACTIVITY NAME	ACTUAL	REMARK
1	Demolishing and Removing existing building	100%	
2	Earth - Cutting & Removing	90%	In progress
3	Piling	100%	Completed
4	Pile cap	100%	Completed
5	Plinth beam	100%	Completed
6	Sump tank		
7	B F Column	100%	Completed
8	L G F Slab	100%	Completed
9	L G F Column	100%	Completed
10	U G F Slab	90%	In progress
11	U G F Column	95%	In progress
12	F F Slab	100%	Completed
13	F F Column	100%	Completed
14	2nd F Slab	100%	Completed
15	2nd F Column	100%	Completed
16	3rd F Slab	100%	Completed
17	3rd F Column	100%	Completed
18	4th F Slab	100%	Completed
19	4th F Column	100%	Completed
20	5th F Slab	100%	Completed
21	5th F Column	100%	Completed
22	6th F Slab	100%	Completed
23	6th F Column	100%	Completed
24	7th F Slab	100%	Completed
25	7th F Column	100%	Completed
26	8th F Slab	100%	Completed
27	8th F Column	100%	Completed
28	9th F Slab	100%	Completed
29	9th F Column	100%	Completed
30	10th F Slab	100%	Completed
31	10th F Column	100%	Completed
32	11th F Slab	100%	Completed
33	11th F Column	100%	Completed
34	12th F Slab	100%	Completed
35	12th F Column	100%	Completed
36	13th F slab	100%	Completed
37	13th F Column	100%	Completed
38	14th F slab	100%	Completed
39	14th F Column	100%	Completed
40	15th F Slab	100%	Completed
41	15th F Column	95%	In progress
42	16th F Slab	50%	In progress

Prepared by

Site in Charge

Approved by

General manager (P)