

SKYLINE FOUNDATIONS & STRUCTURES P (LTD)
MONTHELY PROGRESS REPORT

NAME OF PROJECT : SFS SKY GARDEN

No	ACTIVITY NAME	ACTUAL	REMARK
1	Demolishing and Removing existing building		
2	Earth - Cutting & Removing	98%	lower basement STP
3	Piling	100%	
4	Pile cap & Plinth beam	99%	Lower Basement Ramp area
5	Sump tank	100%	
6	B F Column	98%	Lower Basement Ramp area
7	B F roof Slab	95%	Podium Area
8	G F Column	100%	
9	G F Roof Slab	98%	Podium Area
10	F F Column	100%	
11	F F Roof Slab	95%	Podium Area
12	2nd Floor Column	100%	
13	2nd floor roof slab	100%	
14	3rd Floor columns	100%	
15	3rd floor roof slab	100%	
16	4 th Floor Column	100%	
17	4 th floor roof slab	100%	
18	5 th floor column	100%	
19	5 th floor roof slab	100%	
20	6 th floor column	100%	
21	6 th floor roof slab	100%	
22	7 th floor columns	100%	
23	7 th floor roof slab	100%	
24	8 th floor columns	100%	
25	8 th floor roof slab	100%	
26	9 th floor columns	100%	
27	9 th floor roof slab	100%	

28	10th floor columns	100%	
29	10th floor roof slab	100%	
30	11th floor columns	100%	
31	11th floor roof slab	100%	
32	12th floor columns	75%	
33	12th floor roof slab	20%	work in progress
34	13th floor column		work in progress
35	2nd floor masonry	100%	
36	3rd floor masonry	100%	
37	4 th floor masonry	100%	
38	5th floor masonry	100%	
39	6th floor masonry	100%	
40	7th floor masonry	75%	
41	2nd floor ceiling plastering	100%	
42	2nd floor internal wall plastering	85%	
43	2nd floor electrical switch box fixing	100%	
44	3rd floor electrical switch box fixing	100%	
45	4th floor electrical switch box fixing	100%	
46	5th floor electrical switch box fixing	50%	work in progress

Prepared by
Site in Charge

Approved by