

SKYLINE FOUNDATIONS AND STRUCTURES PRIVATE LIMITED
TRIVANDRUM
PROJECT WORK PROGRESS REPORT - MONTHLY

Common Area work & Amenities.

Name Of Project	West Hill
-----------------	-----------

No	Description	Actual Completion	Remarks
1	C. wall	100%	
2	Gate	100%	
3	Bore well / Open well	100%	
4	Drive way PCC / Flooring	75%	
5	Yard drains	80%	
6	Pest control	90%	
7	Parking area grano flooring	-	
8	Car Park	96%	
9	Sump & OHT	100%	
10	Main stair handrails	100%	
11	Fire stair handrails	100%	
12	External plastering	100%	
13	Duct plastering	100%	
14	Light well plastering	100%	
15	Terrace grano flooring	100%	
16	Light well ladder & platform	100%	
17	Light well roof	100%	
18	Terrace sheet roofing for Bio Bin	98%	
19	Duct plumbing	100%	
20	Terrace water proofing	100%	
21	Terrace plumbing.	100%	
22	External plumbing	100%	
23	Ty. Lobby flooring	100%	
24	Main stair flooring	100%	
25	Fire stair flooring	100%	
26	Lift architrave	100%	
27	Ty. Lobby painting	94%	
28	Ty. Lobby false ceiling	100%	
29	Aluminium duct doors	100%	
30	Fire escape doors	100%	
31	C. Area Doors	100%	
32	Reticulated gas	90%	
33	Fire Fighting	100%	
34	H T Electrical	98%	
35	Lifts	100%	
36	Recreation hall	100%	
37	Common Toilet	100%	
38	Driver's room	100%	
39	Caretaker Room	100%	
40	Party hall	100%	

41	Wheel chair entry to Main lobby	100%	
42	Health club	100%	
43	Fitness equipments	100%	
44	Games room	100%	
45	Shuttle court		
46	Children's play area	100%	
47	Play equipments	100%	
48	Roof top party area	95%	
49	Car park marking	75%	
50	Reflective convex mirror		
51	Yard paving	75%	
52	Letter box		
53	Logos	31-01-2024	
54	Name boards		
55	Key Board		
56	Guest suit		
57	Access card		
58	Intercom	80%	
59	Solar panel for CA lighting	100%	
60	Bio Bin	100%	
61	Rain water harvesting		
62	S T P	99%	
63	Incinerator	100%	
64	Entrance lobby door	100%	
65	Entrance lobby furniture	100%	
66	Entrance lobby art works	100%	
67	Land scaping	90%	
68	External painting	75%	
APARTMENT			
111	LT Works	98%	
112	HT Works	98%	
113	Aluminum fabrication	100%	
114	Steel Fabrication	99%	
115	Carpenter works	98%	
116	Tiling works	98%	
117	Water proofing	100%	
118	1st Coat Putty Apartments	100%	
119	2nd Coat putty Apartments	98%	
120	1st Coat Emulsion	98%	
121	2nd Coat Emulsion	60%	
122	Core Cutting	100%	
123	Fire Systems	100%	
124	Reticulated Gas	90%	
125	False ceiling works	100%	